

ENGINEERING CHANGE NOTICE

DART AEROSPACE LTD

Date: 10.09.08	Job No.: P2010034	ADR Yes/No: NO	ADR Date:	ECN #: 10- 618
Product No.: D212-580	Created By: KB	Approved By: <i>[Signature]</i>		
Product Name: Dual Cargo Mirror and LED Pulse Light Kit	Checked By: DS	General Manager Approval: NA		

Distribution	Reqd	Resp	Initial / Date
Production Manager / Coord.	Y	LL	<i>h 10.10.12</i>
Purchasing Coord.	N		
Production Engineering Coord.	Y	DD/EC	<i>10.10.12</i>

Distribution	Reqd	Resp	Initial / Date
DQA / QA Coord.	N		
QC Coordinator	N		
Customer Technical Support	N		
Marketing	Y	SW	<i>820 10.10.12</i>
Customer Order Processing	N		

Reason for Change:

Release DSI 9532 to correct typo on part number

Documents Affected:

MDL-D212-580 Rev. E
DSI 9532 Rev. A

PARTS MUST COMPLY



PREVIOUS PARTS SATISFACTORY



#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N			
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N			
5	Update Master Document List (MDL)	Y	KB	MDL-D212-580 Rev. E	10.09.08 <i>[Signature]</i>
6	Update Product Compatibility Matrix	N			
7	Create Eurocopter Form (FEE)	N			
8	Notify TC / FAA of Change	N			
9					

#	Document Control Actions	Reqd	Resp	Notes	Complete
10	Move Electronic Files	Y	KJ		10.10.12 <i>[Signature]</i>
11	Update Blue/Pink/DSI Folder and Electronic Files	Y	KJ	Add DSI 9532 Rev. A	10.10.12 <i>[Signature]</i>
12	Update Approved/Preliminary PDF Files	Y	KJ		10.10.12 <i>[Signature]</i>
13	Update Document Record (DR)	Y	KJ	Rev. I	10.10.12 <i>[Signature]</i>
14	Update Product Development Summary	N			
15	Update QSI 021 and/or STC Approval List	N			
16	Update Parts / STC Database	N			
17	Update / Verify ARC Database	N			
18	Create / Update Change Record Form / Item Card Database	N			
19	Create / Update PPP's	N			
20	Update Document Control Database / Laminated Dwgs	N			
21	Update Grey Project / Electronic Binder PDF Files	Y	KJ		10.10.12 <i>[Signature]</i>
22	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		10.10.12 <i>[Signature]</i>
23					
24					

Description / Action:

Update BOM/Routing for D212-580-043 to replace MS27039-217 with ms35206-217 per DSI 9532.

ECN Verified & Complete: *[Signature]*

Date: 10/10/12